

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

DY601
ESE
1/2-1
0.900 mi.
4752 ft.

3094 BRIGHTON 5TH ST
3094 BRIGHTON 5TH ST
BROOKLYN, NY

NY Spills U000398618
N/A

Site 1 of 2 in cluster DY

Relative:
Higher

Actual:
9 ft.

SPILLS:

Name: 3094 BRIGHTON 5TH ST
Address: 3094 BRIGHTON 5TH ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1208555 / 2013-01-23
Facility ID: 1208555
Facility Type: ER
DER Facility ID: 425889
Site ID: 471618
DEC Region: 2
Spill Cause: Deliberate
Spill Class: Not reported
SWIS: 2401
Spill Date: 2012-11-01
Investigator: HRAHMED
Referred To: Not reported
Reported to Dept: 2012-11-02
CID: Not reported
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: DEC
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: Not reported
Remediation Phase: 0
Date Entered In Computer: 2012-11-02
Spill Record Last Update: 2013-09-12
Spiller Name: Not reported
Spiller Company: 3094 Brighton 5th st owner
Spiller Address: Not reported
Spiller Company: 999
Contact Name: "JOSEPH" PROP MGR
DEC Memo: "11/02/12-H.Ahmed-While driving by this location noticed oily water mix in the street by the curb. Tracing back the path of the oily water, found that the building were pumping water from the basement where the oil tank leaked. As the the super Alfred, they were pumping oily water last night and FDNY stopped them and issued summons to pump out oily water on the street. Told him to hire a contractor to pump out the oily water and empty the oil tank for repair or replace.

He said the building manager Joseph (212 447 6848) told him that a contractor is coming tomorrow to pump out the tank.
11/03/12-H.Ahmed-DEC Sharif Rahman went out to the location with a DEC hired contractor and vacuumed out the oily water from the boiler and tank room. 1/23/03- Sandy related, Case closed."
Remarks: "DEC Ahmed walked the street and saw oil. Tracked back to this building. Super(Alfred) was pumping oil/water mix to street on 11/1. FDNY gave them a violation."

All Materials:

Site ID: 471618
Operable Unit ID: 1221474
Operable Unit: 01

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Material ID: 2220123
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported